

HP-41C Functions Bar Codes

Basic function

1/X	
X^2	
SQRT	
Y^X	
E^X	
LN	
10^X	
LOG	
E^X-1	
LN1+X	
BEEP	
TONE	

Basic operator

CHS	
+	
-	
*	
/	
%	
%CH	
Stack & registers	
ENTER^	
X<>Y	
Off	
OFF	

ALPHA

AON	
AOFF	
ASTO	
ARCL	
AVIEW	
ASHF	
Test to zero	
X=0?	
X≠0?	
X>0?	

Clear

CLX	
CLA	
CLD	
CLST	
CLRG	
Numeric entry	
0	
1	
2	
3	
ASN	
CAT	
STAYON	

Made by

Pierre Hardy

<mailto:pierre.hardy@swing.be>

© Pierre Hardy, March 2007

HP-41C Character Set Bar Codes

Byte	Name	LCD	Print	Bar Code	Byte	Name	LCD	Print	Bar Code	Byte	Name	LCD	Print	Bar Code
0	carret	⎵	◆		43	+	+	+		86	V	V	V	
1	small cross	⊗	×		44	,	,	,		87	W	W	W	
2	X bar	⊗	X		45	-	--	-		88	X	X	X	
3	left arrow	⊗	←		46	.	.	.		89	Y	Y	Y	
4	alpha	⊗	α		47	/	/	/		90	Z	Z	Z	
5	beta	⊗	β		48	0	0	0		91	[[[
6	Gamma	⊗	Γ		49	1	1	1		92	\	\	\	
7	down arrow	⊗	↓		50	2	2	2		93]]]	
8	Delta	⊗	Δ		51	3	3	3		94	up arrow	↑	↑	
9	sigma	⊗	σ		52	4	4	4		95	_	_	_	
37	%	⊗	%		80	P	P	P		123	pi	π	π	
38	&	⊗	&		81	Q	Q	Q		124				
39	'	'	'		82	R	R	R		125	right arrow	→	→	
40	(((83	S	S	S		126	Sigma	Σ	Σ	
41)))		84	T	T	T		127	append	⊢	⊢	
42	*	*	*		85	U	U	U						

Made by Pierre Hardy

<http://users.swing.be/id-phy/>

<mailto:pierre.hardy@swing.be>

© Pierre Hardy, March 2007